

CITY OF BALTIMORE WET W SMOKE AND DYED W	Page <u>1</u> of <u>5</u>	
Sewershed: JONES FALLS SEWERSHED	Company: Savin Engineers	Date: 7/22/08
Test to be Performed:	Ground Condition:	Supervisor: GS
Smoke: _X Dyed Water:	Dry: <u>X</u> Damp: Wet:	
Manhole ID: S25GG 041	Test ID: 0994-64 6	Notifications Made: x (Residents, Fire, 311)

Total Length = 310 LF



CITY OF BALTIMORE WET WEATHER CONSENT DECREE Page 2 of 5							of5		
SMOKE AND DYED WA			ATER TESTING FORM				-		
Sewershed: Jones Falls			Compan	ıy: Savin I	Engineers		Date: 7/22/08	}	
Test to	be Performed:			Ground	Condition			Supervisor: GS	
Smoke	e: X Dye	d Water:		Dry: X	Dam	p: Wet	··		
	·							Notifications Made:X	
Manhole ID: S25GG 041		Test ID: 0994-646				(Residents, Fire, 311)			
Field	Sketch: (Show	all Manholes	with Numl	bers, Blov	ver Placei	ment Location,	Sandbag or	Isolation	
Location	ons, Street Nam	es, Building Ad	ldresses a	and Locat	ions, Defe	ect Locations a	nd Photogra	ph Numbers)	
Defect		-		Source			Drainage		Photo
No.		Address		Туре	Location	Sector	Area	Severity	Number
1	539 Bloom Stre	et		16	01	02	50	03	OB01-01
2	539 Bloom Stre	et		16	01	02	25	03	OB01-02
3	535 Bloom Stre	et		16	01	02	75	02	OB02-01
4	531 Bloom Stre	et		03	08	02	10	03	OB03-01
5	537 Bloom Stre	et		16	01	02	100	03	OB04-01
6	2011 Blunt Stre	et		16	12	01	100	02	OB05-01
				OBSER\	/ATION	CODES			
	Source Type	Location	Sector	Severity		Source Type	Location		
01	Main Sewer	Paved Concrete	Public	No Smoke	10	MH Frame Seal	Non-Paved		
02	Service Line	Paved Asphalt	Private	Trace	11	Storm Drain	Field/Woods		
03	Cleanout	Paved Other		Moderate	12	Catch Basin/Inlet	Alley		
04	Downspout	Driveway		Major	13	Storm Manhole	Golf Course		
05	Area Drain	Sidewalk			14	Storm Ditch	Other		
06	Driveway Drain	Curb			15	Excavation			
07	Stairwell Drain	Yard- Front			16	Other			
08	Foundation Drain	Yard-Back							
09	Building Interior	Yard- Side							i

CITY OF BALTIMORE WET W SMOKE AND DYED W	Page <u>3</u> of <u>5</u>	
Sewershed: JONES FALLS SEWERSHED	Company: Savin Engineers	Date: 7/22/08
Test to be Performed:	Ground Condition:	Supervisor: GS
Smoke: _X Dyed Water:	Dry:X Damp: Wet:	
Manhole ID: S25GG 041	Test ID: 0994-646	Notifications Made: x (Residents, Fire, 311)



0994-646_OB01-01



0994-646_OB01-02

CITY OF BALTIMORE WET W SMOKE AND DYED W	Page <u>4</u> of <u>5</u>	
Sewershed: JONES FALLS SEWERSHED	Company: Savin Engineers	Date: 7/22/08
Test to be Performed:	Ground Condition:	Supervisor: GS
Smoke: _X Dyed Water:	Dry: X Damp: Wet:	
Manhole ID: S25GG 041	Test ID: 0994-646	Notifications Made: x (Residents, Fire, 311)



0994-646_OB02-01



0994-646_OB03-01

CITY OF BALTIMORE WET W SMOKE AND DYED W	Page <u>5</u> of <u>5</u>	
Sewershed: JONES FALLS SEWERSHED	Company: Savin Engineers	Date: 7/22/08
Test to be Performed:	Ground Condition:	Supervisor: GS
Smoke: _X Dyed Water:	Dry:X Damp: Wet:	
Manhole ID: S25GG 041	Test ID: 0994-646	Notifications Made: x (Residents, Fire, 311)



0994-646_OB04-01



0994-646_OB5-01